National Transportation Safety Board FACTUAL REPERT AVIATION

NTSB ID: SEA05RA139

Aircraft Registration Number: N236AC

Occurrence Date: 07/06/2005

Most Critical Injury: Fatal

Occurrence Type: Accident

Investigated By:

Location/Time

Nearest City/Place	State	Zip Code	Local Time	Time Zone	
Rome			1630		
Airport Proximity:	Distance From	From Landing Facility:		Direction Fro	m Airport:

Aircraft Information Summary

Aircraft Manufacturer	Model/Series	Type of Aircraft
Erickson Air-Crane, Inc.	S-64F	Helicopter

Sightseeing Flight: No Air Medical Transport Flight: No

Narrative

Brief narrative statement of facts, conditions and circumstances pertinent to the accident/incident:

On July 6, 2005, at approximately 1630 Central European Summer Time, an Erickson Air-Crane, Inc., S-64F helicopter, N236AC, was destroyed following impact with terrain and postimpact fire at Fiumicino International Airport, Rome, Italy. A maintenance crew chief was fatally injured; however the commercial pilot and a second maintenance crew chief received minor injuries, while an Italian National copilot received serious injuries. Visual meteorological conditions prevailed for the cross-country flight that was originating at the time of the accident; their destination was Ciampino Airport, approximately 10 nautical miles away.

The helicopter was hovering at approximately 60 to 75 feet while performing a hydraulic check. The American pilot was reading the checklist while the Italian National pilot was flying. The American pilot reported that the helicopter suddenly pitched up approximately 75 degrees, fell backwards permitting the antitorque rotor to impact the asphalt. He said that the aircraft rolled on its left side and immediately started to burn. The survivors escaped out the right hand pilot window.

The accident is under the jurisdiction of the Italian government's Agenzia Nazionale per la Sicurezza del Volo (ANSV). Further information can be obtained from:

ANSV,

Ing. Gianluigi Guanziroli,
Via A. Benigni, 53,
00156 Rome, Italy.

National Transportation Safety Board FACTUAL REPORT AVIATION

NTSB ID: SEA05RA139

Occurrence Date: 07/06/2005

AVIATION		Occurrence Type: Accident										
Landing Facility/Approach In	formation					'						
Airport Name			Airport ID:	Airport Eleva	ation	Run	way Used	Runwa	Runway Length		Runv	vay Width
			·		. MSL							
Down Out to a Town										[
Runway Surface Type:												
Runway Surface Condition:												
T 1												
Type Instrument Approach:												
VFR Approach/Landing:												
11												
Aircraft Information												
Aircraft Manufacturer			Mode	l/Series					Serial	Numbe	er	
Erickson Air-Crane, Inc.			S-64	F								
Airworthiness Certificate(s):			-									
Landing Gear Type:	Landing Gear Type:											
Homebuilt Aircraft? No	No Number of Seats:				Certified Max Gross Wt.			LBS Numbe			gines	:
Engine Type: Er				Engine Manufacturer: Model/Series:							Rate	ed Power:
- Aircraft Inspection Information										·		
Type of Last Inspection			Date of Last Inspection Time			Time Sir	ime Since Last Inspection				ne To	tal Time
							Hours				Hours	
- Emergency Locator Transmitter (ELT) Information											
ELT Installed?	ELT Opera	ted?			ELT	Aided in	n Locating Ac	cident S	ite?			
Owner/Operator Information												
Registered Aircraft Owner			Street	Address								
Ü												
			City	City							ie	Zip Code
			Street A	Address						<u>. </u>		
Operator of Aircraft 3100 Willow Springs Road												
Erickson Air-Crane, Inc.				City						Stat	te	Zip Code
Operator Does Business As:				Central Point OR 97502 Operator Designator Code:							97502	
- Type of U.S. Certificate(s) Held: None												
Air Carrier Operating Certificate(s)												
Operating Certificate:				Operator (Certific	ate:						
Regulation Flight Conducted Under: Part 91: General Aviation												
Type of Flight Operation Conducted												
• • • • • • • • • • • • • • • • • •	,											_
		FACTU	JAL REPO	ORT - AVIAT	ION							Page 2

National Transportation Safety Board

FACTUAL REPORT

AVIATION

NTSB ID: SEA05RA139

Occurrence Date: 07/06/2005

AVIATION Occurrence Type: Accident						ccident								
First Pilo	t Information													
Name						City					Stat	te [Date of Birth	Age
On File														
Sex: Seat Occupied: Principal Profession:										Cer	tificat	e Numb	er: On File	
Certificate((s):													
Airplane R	ating(s):													
Rotorcraft/	Glider/LTA:													
Instrument	Rating(s):													
Instructor F	Rating(s):													
Type Rating/Endorsement for Accident/Incident Aircraft? Current Biennial Flight Review?														
Medical Ce	ert.:	Medica	al Cert. Status	3:						ate of La	st Me	edical Ex	am:	
- Flight Tin	ne Matrix	All A/C	This Make and Model	Airplane Single Engine	Airplane Mult-Engine	Night		Actual	Instrumer	Instrument Rotorcraft Simulated			Glider	Lighter Than Air
Total Time	!													
Pilot In Co	mmand(PIC)										\perp			
Instructor											\perp			
Last 90 Da	ays													
Last 30 Da	-										+			
Last 24 Ho	ours	<u> </u>												
Seatbelt U	sed?	Shou	ılder Harness	Used?		Τ	oxico	ology Pe	erforme	ed?		Se	cond Pilot?	
	an/Itinerary													
	ght Plan Filed: N	one												T
Departure Point Same as Accident/Incident Location							State		Airport Identifier FCO		r	Depart 1630	ture Time	Time Zone
Ciampino							State Airport Identifier							
Type of Clo	earance:							I						
Type of Air	rspace:													
Weather	Information													
Source of	Briefing:													
Method of	Briefing:													
				FACTUAL	BED∪D⊥	_ Δ \/ Ι Δ '	TION	vi						Page 3
				TACTUAL	KLFUKI	- AVIA	1101	٧.						i age o

National Transportation Safety Board FACTUAL REPORT AVIATION

NTSB ID: SEA05RA139

Occurrence Date: 07/06/2005

	AVIATION			Occurrence Type: Accident							
Weather Information											
WOF ID	Observation Time	Time Zone	\	WOF Eleva	ition	WOF D	WOF Distance From Accident Site				Direction From Accident Site
				F	t. MSL				NM		Deg. Mag.
Sky/Lowes	st Cloud Condition:						Ft. AG	BL .	Condition o	of Ligh	nt:
Lowest Ce	eiling:			F	t. AGL	Visib	ility:		SM Altimeter:		
Temperatu	ure: °C	Dew Point:		°C	Wind	Direction:	:			Dei	nsity Altitude: Ft.
Wind Spee	ed:	Gusts:			Weat	her Condt	ions at Accid	dent Si	ite: Visual C	Cond	itions
Visibility (R	RVR): Ft.	Visibility	/ (RVV	′)	SM	Intensit	y of Precipita	ation:			
Restriction	ns to Visibility:										
Type of Pre	ecipitation:		_							_	
Accident	Information										
Aircraft Dar	mage: Destroyed			Aircraft F	ire:				Aircraft Exp	losio	n
Classificati	ion:										
- Injury Sur	mmary Matrix	Fatal	Seriou	us Mir	nor	None	TOTAL				
First Pi	ilot				1		1]			
Second	d Pilot			1			1]			
Studen	nt Pilot							1			
Flight I	nstructor							1			
Check	Pilot							1			
Flight E	Engineer]			
Cabin /	Attendants]			
Other C]			
Passen	ngers	1				1	2	1			
- TOTAL /	ABOARD -	1		1	1	1	4	1			
Other G								1			
- GRANE	D TOTAL -	1		1	1	1	4	1			
				·							

National Transportation Safety Board

FACTUAL REPORT AVIATION NTSB ID: SEA05RA139

Occurrence Date: 07/06/2005

Occurrence Type: Accident

istrative	

Investigator-In-Charge (IIC)

James F. Struhsaker

Additional Persons Participating in This Accident/Incident Investigation:

Gianluigi Guaziroli Rome, Italy